




Pitting at the water line



Pitting in area of copper deposition
Below the water line

Pitting Corrosion of Cast Aluminium Cistern due to Deposition of Copper Ions